

Bygrove School Newsletter

New Extension



During the recent consultation with the Key Stakeholders group we found out what you want you would like the design of you school to include.

You told us that –

Functionality

The nursery playground does not function well as a space, as well as the larger playground as there is no segregation of space for different types of play.

The school entrance is too small which causes a bottle nose effect at the beginning and end of the school day.

The ICT suite is only designed for 15 children not a full class of 30.

There is a general lack of storage in the school.

Maintenance Resources/Burdens

Heating in the school is not zoned at all and areas are often to hot.

Asbestos

Concern over additional maintenance



Local Traffic & Transport Implications

Entrance congestion at school start and finish was discussed.

Other transport and traffic will remain the same, Stakeholders where happy with existing traffic around the school.

Building User Satisfaction

The children find the classrooms dark.

There are no SEN areas of the school so this limits the abilities of the children that can be admitted to the school.



Shared use of Facilities

Language classes

Family Literacy

Parenting Classes

Cookery Lessons



Management & Operational Implications

New doors can cause hazards to children by them trapping their fingers in them. Manage this with providing all new doors with finger traps.

The group expressed concern over the loss of space during the build. This will be managed by the school and the design team together phasing works.



Learning Resources

Nesting Boxes

Solar Panels

Wind Turbine

Rainwater Harvesting

Rainwater Measurement



School Grounds

Tree roots causing lifted asphalt causing puddles and trip hazards

More equipment for children

